Individually Priced Repairs for Mobile Scanners

Eco Rate for common repairs, and Cap on severely damaged units.

	Price
For example, if device only requires Touch-Screen Replacement, your repair cost is $45. Instead of the higher old flat rate price (usually $150-$350), you are only paying $45.	
Windows Device Touch-Screen Replacement	**$45.00**
Android Device Touch-Screen Replacement	**$55.00 - $195.00**
Trigger Replacement / Repair	**$45.00**
Scanner Exit Window Replacement	**$30.00**
Speaker Replacement	**$45.00**
Internal Backup Battery Replacement	**$30.00**
Color LCD Display Replacement (Dependant on Model - Please Email your part number to confirm device's LCD replacement cost)	**$75.00 - $195.00**
Keypad Repair / Replacement	**$95.00**
Top Shell Replacement	**$95.00**
Bottom Shell Replacement	**$95.00**
Keyboard Ribbon-Flex Replacement	**$50.00**
Scan Engine Ribbon Flex Replacement	**$45.00**
Scan Engine Replacement (Dependant on Model - Please Email your part number to confirm device's Scan Engine replacement cost)	**$45.00 - $195.00**
LCD Display Ribbon Flex Replacement	**$45.00**
Battery Pins Repair / Replacement	**$75.00**
Bottom Communication Connector Repair / Replacement	**$75.00**
CPU Mainboard replacement (Dependant on Model Series - Please Email your part number to confirm CPU replacement cost)	**$100.00 - $995.00**
<u>All Repairs include</u> - Turnaround 3-10 working days in shop, 100 Day Warranty on repairs performed.	
<u>Repair Cap-Off</u> - not to exceed $275.00 for any device requiring multiple repairs to fix. CPU MainBoard failure/replacement is the only part NOT covered by the Cap)	**$275.00**

Bottomline: no contract, no pre-payment, no minimum. You pay for the repair you require at a reasonable pre-determined rate.